

**Boulevard 3 Base Raceway Distribution housing installation**

Please note that in some cases the Power Distribution Housing will not install properly into the pre-punched location holes on the Raceway extrusion in Boulevard 3 series panels.

The standard Power Distribution Housing has 2 extended bolts that normally locate into pre-punched holes in the extrusion of the base raceway. As shown below.



If the alignment is not correct, you may have to retrofit the Power Distribution Housing.

Method 2. You may "cut" the protruding bolts from the existing hardware so that only 1/16" extends beyond the hardware.

Method 1. You can contact the Claims Department at Global Contract Inc. for replacement bolts that are smaller and will not extend into the panel opening. This will require that the existing bolts be removed from the hardware at each end of the Distribution Housing and then re-assembled with provided part.

Your completed distribution housing should look like image below.



To install in correct position of the panel, please use the raceway covers as a guide to position. Install duplex receptacles into Power Distribution Housing and line up with openings in the raceway.

Please note that this is a temporary problem and will require only a temporary solution.

Global Contract Inc.  
565 Petrolia Rd.  
(416) 739-5000  
claims@globalcontract.com